

2003 Schedule of Programs

Quarterly Lab Survey Schedule

Quarterly Report Period	Mailout Target Date	Due Date
1 st Cycle	January 13, 2003	February 14, 2003
2 nd Cycle	April 14, 2003	May 16, 2003
3 rd Cycle	July 14, 2003	August 15, 2003
4 th Cycle	October 14, 2003	November 14, 2003

Associate Users Audit

Year	Mailout Target Date	Due Date
2002	June 2, 2003	July 3, 2003

Leak Test Schedule

Mailout Cycle	Mailout Target Date	Due Date
1 st Leak Test	January 13, 2003	February 14, 2003
2 nd Leak Test	July 14, 2003	August 15, 2003

X-Ray Producing Equipment Annual Inventory Audit

Year	Mailout Target Date	Due Date
2002	June 2, 2003	July 3, 2003

Sealed Source Inventory Audit

Audit Period	Mailout Target Date	Due Date
1 st Inventory Audit	February 3, 2003	March 3, 2003
2 nd Inventory Audit	August 4, 2003	September 5, 2003

Irradiator Survey

Survey Period	Mailout Target Date	Due Date
1 st Survey	January 14, 2003	February 14, 2003
2 nd Survey	July 14, 2003	August 15, 2003

LRPO Radioactive Waste Manifests

Survey Period	Mailout Target Date	Due Date
1 st Survey	February 3, 2003	March 3, 2003
2 nd Survey	August 4, 2003	September 5, 2003

Incineration Report

Audit Period	Mailout Target Date	Due Date
1 st Inventory Audit	February 10, 2003	March 10, 2003
2 nd Inventory Audit	May 12, 2003	June 13, 2003
3 rd Inventory Audit	August 11, 2003	September 12, 2003
4 th Inventory Audit	November 10, 2003	December 12, 2003